



SAS Superstructure

Location: 04-SF-80-13.2 / 13.9

Client Name: CalTrans

Run date 19-Nov-14

Time 4:15 PM

Daily Diary Report by Bid Item

Contract No.: 04-0120F4

Diary #: 045 Const Calendar Day: 222 Date: 18-Apr-2010 Sunday

Inspector Name: Altamirano, Victor Title: Transportation Engineer

Inspection Type:

Shift Hours: Break: Over Time:

Federal ID:

Location:

Reviewer: Liu, Tai-Lin Approved Date: 30-Apr-10 Status: Approved

04-0120F4
04-SF-80-13.2/13.9
Self-Anchored
Suspension Bridge

Weather

Temperature 7 AM 50 - 60 12 PM 50 - 60 4PM 50 - 60

Precipitation

Condition

Working Day ☒ If no, explain:

Diary:

Dispute

Work description.

Field Work:

I arrived at Pier 7 at 11am and the second OBG shipment had already arrived before I got to the pier. I took several pictures showing the operations. Mainly workers were placing equipment, such as, manlifts, steel storage boxes, ladders and etc. The weather was sunny and clear about 70 degrees. The pictures are mainly to provide a visual of the OBG conditions based on the limited access I had from Pier 7. The pictures indicate the operations conducted by the iron workers after the shipment arrival. Pictures were taken behind fencing at Pier 7.

Hours Worked: 5 hours total overtime.

